


CONNECTS 1/4" POLY TUBING TO COMPRESSION FITTINGS AND VALVES



CAUTION: Turn off electricity at circuit breaker before working on evaporative cooler.

Poly Tubing: 1. Cut the end of the poly tube square to insure proper fit. 2. Place barbed adapter through nut and tighten onto fitting with a wrench. 3. Push poly tube onto barbed adapter.

CONECTA MANGUERA DE 1/4" A CONECTORES Y VÁLVULAS A COMPRESIÓN

PRECAUCIÓN: Desconecte la electricidad de la caja de interruptores antes de trabajar en un enfriador evaporativo.

Manguera: 1. Corte el extremo del tubo derecho para asegurar un acoplamiento adecuado. 2. Ponga el adaptador barbado dentro de la tuerca y apriete en el conector con una llave de tuerca. 3. Empuje la manguera sobre el adaptador barbado.

⚠ **WARNING:** Cancer and Reproductive Harm - www.P65Warnings.ca.gov.

⚠ **ADVERTENCIA:** Cáncer y Daño Reproductivo - www.P65Warnings.ca.gov.

www.dialmfg.com Made in China 

© Copyright 2019 Dial Mfg., Inc. Phoenix, AZ